

30–34. (Figs. 17.52–17.56) Full sections: Complete the drawings as full sections. Draw one problem per Size A sheet. Each grid equals 0.20 inch or 5 mm. Show the cutting planes when they are not given.




Figure 17.52 Problem 30. Full section.




Figure 17.55 Problem 33. Full section.