


DRAFTING
MACHINE



RED VERTICAL RAIL AND PROTRACTOR HEAD
LOCKS REMAIN UNLOCKED. ALWAYS CHECK.
PROTRACTOR LOCK #1 TO BE KEPT LOCKED.
LOCK AND UNLOCK PROTRACTOR LOCKS #2
AND #3

LOCK GENTLY TO FIRM BEARING.

NEVER FORCE A LOCK; NEVER FORCE
MOVEMENT AGAINST A LOCK.